

GOVERNMENT OF TELANGANA

ABSTRACT

Public Services - I&CAD Department – Allegations of irregularities noticed in allowing substandard work in Formation of new Tank Across Yerrasani Vagu Near Chandrulagudem(V), Polvancha (M) in Khammam District – Disciplinary proceedings initiated against Sri M. Sammi Reddy, EE(Retd.) and (2) others – Inquiry conducted – Further action dropped — Orders – Issued.

IRRIGATION & C.A.D. (Vig.II-A1) DEPARTMENT

G.O.RT.No. 923

Dated: 28-12-2015
Read the following:

1. From the GA (V&E) Dept. Vigilance Report No. 30 (1201/V& E/E1/2004, date 28-2-2005.
2. Govt. Memo No.11555/SerVII(V&E)A1/2015-2, dt. 13-05-205
3. G.O.Rt.No. 89, 90 & 91, I & C.A.D. {Ser.VII (V&E-1} Dept. Dated: 22 -01-2007.
4. WSD from Sri M. Sammi Reddy, EE(Retd. Dt. 15-02-2007.
5. WSD from Sri P. Srinivasa Reddy, Dy. EE Dt.15-2-2007.
6. WSD from Sri S. Satish Kumar, Dy.EE Dt. 15-02-2007.
7. G.O.Rt.No. 787, I&CAD (Ser.VII(V&E)A1) Dept., Dt. 20-06-2008
8. From Sri Janak Raj, I.P.S.(Retd.) D.O.Lr.No. 1021/COI-JR/2008, Dt. 16-12-2009.
9. Govt. Memo No. 11555/Ser.VII(V&E)A1/2005-27,34, 38 & 41 Dt.05-10-2010, 09-09-2011, 13-10-2012 & 5-11-2013
10. From the Chief Engineer, Minor Irrigation, Hyderabad Lr.No.CE(MI)/DCE.Spl/OT(D)/AEE4/TSP/KHM/08, Dt. 09-08-2011, 21-12-2013 & 08-10-2015.

* * *

O R D E R

In the reference 1st read above, it has been brought to the notice of the Government that certain allegations of irregularities noticed in allowing substandard work in Formation of new Tank Across Yerrasani Vagu Near Chandrulagudem(V) Polvancha (M) in Khammam District. with a recommendation to initiate disciplinary action against the engineers responsible.

2. After examination of the matter, it has been decided to initiate disciplinary action against the engineers responsible. Accordingly, in the reference 3rd read above, disciplinary proceedings have been initiated against the following engineers by way of issuing articles of charges with a direction to submit their Written Statements of Defence thereon.

1. Sri M. Sammi Reddy, EE(Retd.)
2. Sri P. Srinivasa Reddy, Dy.EE
3. Sri S. Satish Kumar, Dy.EE

3. In the reference 4th to 6th read above, the above said Charged Officers have submitted their Written Statements of Defence, denying the charges framed against them.

4. After examining the Written Statements of Defence, it has been decided to conduct an inquiry into the charges framed against them, as their WSD are not convincing. Accordingly, in the reference 7th read above, orders have been issued by appointing Sri Janak Raj, IPS(Retd.), Member, COI as Inquiring Authority to conduct a detailed enquiry into the charges framed against Sri M. Sammi Reddy, EE (Retd.) and others.

::2::

5. In the reference 8th read above, the Inquiring Authority has submitted his enquiry report stating that the charges framed against the above said (3) charged officers are held as not proved.

6. On receipt of the inquiry report, the Chief Engineer, Minor Irrigation, Hyderabad has been requested to expedite his report on the observations and recommendations of the D.G., G.A.(V&E) Dept. in the reference first read above, as the charges framed against the COs are related to the pending report on the soil test etc.

7. In the reference 10th read above, the Chief Engineer, Minor Irrigation, Hyderabad has furnished the report of Chief Engineer, CDO wherein it has been reported that, the small dams under category Embankments where the height is below and upto 5.00m and Embankments where the height is more than 5.00m and up to 10.0m stability analysis may not be necessary and based on the guidelines and available data, the stability of entire bund cannot be established, however inference is drawn for available date for three sections out of eighteen sections sought and summarized that only side slopes are not confirmed to IS 12169 – 1987. As per the Chief Engineer, CDO report, out of eighteen (18) sections selected for analysis in three (3) sections on R/s of weir at 1) Ch:20.0m, 2) 80.0m and chainages on L/s of weir at 3) 45.0m are not confirming to IS 12169-1987, as seen from above locations the height of bund is 5.045m, 5.175m and 2.120m respectively. The Chief Engineer, CDO mentioned that for small embankments upto 10.0m height stability analysis may not be necessary. Thus, the stability analysis for the above three sections is not necessary as per IS 12169-1987.

8. After careful examination of the entire matter, it has been decided to drop further action against Sri M. Sami Reddy, EE(Retd.) and (2) other engineers referred at Para (2) above, as the charges framed against them are held as not proved in respect of the allegations of irregularities noticed in allowing substandard work in Formation of new Tank Across Yerrasani Vagu Near Chandrulagudem(V), Polvan cha (M) in Khammam District. Accordingly, Govt. hereby drop further action against Sri M. Sami Reddy, EE(Retd.), Sri S. Satish Kumar, Dy.EE now I/C EE, and Sri P. Srinivasa Reddy, Dy.EE(Retd.).

9. The Irrigation & CAD(Ser.I/II) Department / the Engineer-in-Chief (AW), I&CAD Department, Hyderabad shall take further necessary action in the matter accordingly.

(BY ORDER AND IN THE NAME OF THE GOVERNOR OF TELANGANA)

**SHAILENDRA KUMAR JOSHI
PRINCIPAL SECRETARY TO GOVERNMENT**

To

The Individuals concerned through the Engineer-in-Chief(AW) , I&CAD Department, Hyderabad .

The Engineer-in-Chief(AW) , I&CAD Department, Hyderabad.

The I&CAD (Ser. I&II) Department.

Copy to:

The Accountant General, T.S., Hyderabad.

The General Administration (V&E) Department, BRK Buildings, Hyderabad

The Secretary to VC, T VC, Hyderabad.

The Govt. Pleader for I &CAD Dept., APAT, Hyderabad

(w.r.to C.A.1849/2013 in O.A.No.9842/2011).

SF/SC

//FORWARDED : BY ORDER//

SECTION OFFICER